

Every Day Concrete Problems Are No Problem With DuraQuartz







EC-023











The facilities' engineers of a major pharmaceutical firm located in New Jersey, were "extremely impressed" with the professionalism and rapid response of the local ENECON Mid Atlantic Field Engineering Team. As these pictures illustrate, this routine yet potentially dangerous concrete problem was quickly repaired with ENECRETE DuraQuartz.

Forms were used to "shutter" the DuraQuartz repair. After these were removed, SpeedAlloy was used to fill in any irregularities in the DuraQuartz surface.

The repaired areas were then sanded and a coat of FPS was applied to finish off the repair and make it look "perfect".

700 Hicksville Road • ENECON Center Suite 110 • Bethpage, New York 11714 Toll Free: 888-4-ENECON • Phone: 516.349.0022 • Fax: 516.349.5522 Website: www.enecon.com • Email: info@enecon.com