



ENESEAL CR Prescribed to Repair Northern California Hospital's Cooling Tower Piping & Electrical Cabinets




Client: Northern CA Hospital

Problem: Due to neglect and lack of maintenance, these cooling tower pipes and electrical cabinets were suffering from severe corrosion.

Solution: Extremely corroded areas were prepared by wire wheel brush followed by high pressure washing. Two coats of **ENESEAL CR** were then spray-applied providing years of corrosion and UV protection.

Cost: This \$70,000 turn-key project was completed in just one week and has now led to protecting other areas of the hospital suffering from similar conditions.



6 Platinum Court • Medford, NY 11763
Toll Free: 888-4-ENECON[®] (888-436-3266) • Phone: 516-349-0022 • Fax: 516-349-5522
www.enecon.com • info@enecon.com