

Pharmaceutical Manufacturer In Cyprus Repairs Problem Floor Areas With ENECRETE DuraFill & CHEMCLAD GP



A local pharmaceutical manufacturing company in Cyprus was experiencing problems with the floor in its warehouse.

The maintenance team was familiar with ENECON products and contacted ENECON Mesogios to repair these critical flooring problems.


The damage in these areas caused issues with the heavy forklifts that passed through these warehouse areas to load and unload pallets of medicine throughout the day.

DuraFill mixed with silica sand was used to

resurface missing concrete.

Finally, according to the client's requirements, the area was topped with CHEMCLAD GP in a haze-gray color.

The client was happy because the repairs not only provided a safer environment for the employees but also a great-looking floor for future inspections.



6 Platinum Court • Medford, NY 11763
Toll Free: 888-4-ENECON[®] (888-436-3266) • Phone: 516-349-0022 • Fax: 516-349-5522
www.enecon.com • info@enecon.com