

## CHEMCLAD SC Eliminates Corrosion On Steel Mill Ammonia Storage Tanks



Very large ammonia storage tanks located at a steel manufacturing plant in northern India were severely corroded after years of exposure to chemical fumes and atmospheric corrosion. The plant's maintenance engineers were in need of a chemical resistant solution.

The local ENECON Distributor in the region had previously arranged for the plant to conduct internal testing of ENECON's

*CHEMCLAD SC*. The SC exceeded the plant's expectations so it was the obvious choice to solve this corrosion issue.

All previous failed coatings were removed by grinding the tanks surface. A two coat system of CHEMCLAD SC was applied to protect the surface from future corrosion. The engineers were so pleased with the results, future projects have already been planned.



6 Platinum Court • Medford, NY 11763  
Toll Free: 888-4-ENECON<sup>®</sup> (888-436-3266) • Phone: 516-349-0022 • Fax: 516-349-5522  
[www.enecon.com](http://www.enecon.com) • [info@enecon.com](mailto:info@enecon.com)